



PREXISO P50


LASER DISTANCE METER



Measure



2 sec



+ -

+ / -

C 

OFF



+

-



→ OFF



Units



2 sec


Switch between
the following units:

0.000 m

0'00" 1/16


0 in 1/16

Batteries








1x: Area



2x: Volume



3x: Pythagoras 2-point





Laser class 2 in acc. to IEC 60825-1



LCAB12803

www.prexiso.com

PREXISO